


DETAIL 1902



Notes:

•

- Scupper must be securely fastened to the scupper opening with a minimum of 8 True Seal™ approved fasteners.
- Scupper flanges must have a minimum of 2 True Seal™ approved fasteners.
- At all times, the seam overlap area must be dry before field seam hot air welding
- At all times, the seam overlap area must be free of dirt, debris and contaminates before field seam hot air welding.
- Scupper should be seated in the opening to promote positive drainage and not hold water back-up on the roof area.
- Clad metal scuppers must be sized and engineered to provide the adequate run-off (drainage) yields as required by the local building code.

WWW.TRUE-SEAL.COM

NTS - Rev: Oct 2018